



FIG. 1



F I G. 2 A



F I G. 2 B




FIG. 3A




FIG. 3B




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16A




FIG. 16B




FIG. 18




FIG. 19




FIG. 20




FIG. 21A




FIG. 21B




FIG. 21C




FIG. 21D




FIG. 21E




FIG. 21F




FIG. 21G




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30





FIG. 31






FIG. 32A: UPPER AND LOWER WORK SET




FIG. 32G: FINE ALIGNMENT




FIG. 32B: REDUCED PRESSURE




FIG. 32H: BONDING




FIG. 32C: LOWER WORK
PLASMA TREATMENT




FIG. 32I: LIFT HEAD




FIG. 32D: UPPER WORK
PLASMA TREATMENT




FIG. 32J: RETURN STAGE,
RELEASE ATMOSPHERE




FIG. 32E: ALIGNMENT




FIG. 32K: REMOVE WORK




FIG. 32F: SLIDE STAGE